



2007 SERVICE BULLETIN INDEX

BY MODEL / SECTION /SERVICE BULLETIN #

5/7/2007

MODEL	SEC-BUL#	DATE	SUBJECT	RI#
B-SERIES				
	01 - 004/07	2/2/07	MIL COMES ON WITH DTC P0462	5352
	01 - 005/07	4/3/07	MIL COMES ON WITH DTC P0607	5355
	01 - 006/07	2/8/07	MIL ON WITH DTC P0401	5209
	05 - 002/07	3/14/07	MERCON® ATF IS BEING REPLACED BY MERCON® V AS A SERVICE FLUID FOR MANUAL TRANSMISSIONS	5427
CX-7				
	01 - 007/07	2/8/07	MIL ON WITH DTCs P0201 / P0204 / P0300 - PCM CONNECTOR INSTALLATION CAUTION	5323
	02 - 001/07	3/16/07	STEERING PULL / DRIFT - IMPROVED DIAGNOSTIC AND REPAIR PROCEDURE	5176
CX-9				
	02 - 003/07	4/17/07	STEERING PULL / DRIFT	5399
	09 - 003/07	2/12/07	LIFTGATE GLASS REPLACEMENT CAUTION - SERVICE TIP	5370
	09 - 004/07	2/12/07	ROOM FUSE LOCATION - SERVICE TIP	5357
	09 - 015/07	4/17/07	CHECK FUEL CAP WARNING LIGHT	5464
	09 - 016/07	5/7/07	GREASE SEEPS FROM AUDIO PANEL	5476
	ST - 001/07	2/15/07	SPECIAL SERVICE TOOL SHIPMENT - FEBRUARY 2007	5378
MAZDA3				
	01 - 008/07	2/8/07	ENGINE STALL AND HESITATION AFTER START-UP UNDER HIGH AMBIENT TEMPERATURE	5373
	01 - 018/07	5/7/07	NO START DUE TO FROZEN MAIN RELAY	4565
	04 - 001/07	2/8/07	ABS WARNING LIGHT ON WITH DTC C1141, C1142, C1233, OR C1234/GRINDING NOISE FROM FRONT WHEELS	4739
	08 - 001/07	3/30/07	AIRBAG WARNING LIGHT COMES ON WITH CODE B1877/B1881	5382
MAZDA5				

BY MODEL / SECTION /SERVICE BULLETIN #**5/7/2007**

MODEL	SEC-BUL#	DATE	SUBJECT	RI#
	09 - 041/06	10/12/06	DRIVER'S DOOR DOES NOT LOCK	5134
	ST - 002/07	3/28/07	SPECIAL SERVICE TOOL SHIPMENT - MARCH 2007	5445
MAZDA6				
	01 - 009/07	2/22/07	ENGINE NO START DUE TO FROZEN MAIN RELAY / FUEL PUMP RELAY	5263
	01 - 012/07	5/7/07	TICKING NOISE FROM PURGE VALVE	4967
	01 - 017/07	4/30/07	ENGINE STALL AT LOW SPEED	5307
	06 - 001/07	2/22/07	UNUSUAL NOISE FROM STEERING SHAFT WHEN TURNING STEERING WHEEL	4963
MAZDASPEED6				
	05 - 003/07	4/27/07	CLUTCH PEDAL IS DIFFICULT TO OPERATE	5498
MPV				
	01 - 003/07	2/2/07	MIL ILLUMINATION WITH DTCS P2404 / P0446	3816
	04 - 002/07	2/15/07	SQUEAKING / GRINDING NOISE FROM REAR BRAKES	4512
MULTI				
	01 - 001/07	1/3/07	MAZDA SPECIAL PROGRAM (MSP13) - MIL ILLUMINATION WITH DTC P0455	5313
	01 - 010/07	3/1/07	MIL COMES ON WITH DTC P2006 (VARIABLE SWIRL CONTROL SYSTEM SHUTTER VALVE STUCK CLOSED)	5348
	01 - 013/07	4/5/07	NO START/LOSS OF ENGINE TIMING/SCRAPING NOISE AT CRANKSHAFT PULLEY/POSSIBLE ENGINE DAMAGE	5089
	05 - 001/07	2/15/07	MERCON® ATF IS BEING REPLACED BY MERCON® V AS A SERVICE FLUID FOR A/T & POWER STEERING	5197
	09 - 005/07	2/15/07	NAVIGATION SYSTEM DISPLAYS NO MAP OR INCORRECT MAP	4877
	09 - 009/07	3/14/07	ODOMETER DATA CONFIGURATION - SERVICE TIP	4888
	09 - 012/07	3/30/07	ENGINE UNDERCOVER HARD TO REMOVE	5374
	ST - 003/07	4/18/07	SPECIAL SERVICE TOOL BULLETIN - AVAILABILITY OF NON-REQUIRED TOOLS - APRIL 2007	5479
MX-5				

BY MODEL / SECTION /SERVICE BULLETIN #**5/7/2007**

MODEL	SEC-BUL#	DATE	SUBJECT	RI#
	09 - 001/07	4/17/07	WATER ACCUMULATION IN FOOTWELL / PLUGGED SOFT TOP DRAINS	5320
	09 - 006/07	2/15/07	GAP APPEARS IN HARD PLASTIC DOOR TRIM PANELS	5302
	09 - 007/07	2/22/07	CENTER CONSOLE SIDE WALL REMOVAL CAUTION - SERVICE TIP	5387
	09 - 010/07	3/21/07	AM RADIO - POOR RECEPTION	5429
	09 - 011/07	3/28/07	POPPING NOISE FROM RADIO WHEN PASSING OVER BUMPS	5343

PROTEGE

	01 - 002/07	1/11/07	MAZDASPEED - WHISTLE NOISE AT IDLE, FUEL CUT UNDER BOOST, MIL ILLUMINATED, DTC P0171 SET	4383
	01 - 011/07	3/12/07	MAZDASPEED - CONVERTER ASSEMBLY BREAKS AT WELD	5322

RX8

	01 - 014/07	4/5/07	MIL ILLUMINATED - P2004 SET	5432
	01 - 015/07	4/5/07	MIL ILLUMINATED - P0126 SET - THERMOSTAT MONITOR	5333
	01 - 016/07	4/30/07	IGNITION COIL INSPECTION	5258
	09 - 002/07	2/2/07	SUNVISOR PIVOT BROKEN	5303
	09 - 013/07	4/3/07	TRUNK LID REQUEST SWITCH INOPERATIVE	5388
	09 - 014/07	4/13/07	WATER IN REAR COMBINATION LIGHT	4721

TRIBUTE

	02 - 002/07	1/25/07	SQUEAK / CREAK NOISE FROM REAR OF VEHICLE	5314
	05 - 004/07	4/27/07	ENGINE STALLS ON ENGAGEMENT / STOPPING	5354